



---

## Product Change Notification

**PCN No: 2007-08-01-01**

**Report Date: August 01, 2007**

**Subject: GLK12232-25-SM PCB 1.4 Firmware Change**

---

### List of New / Changed Products:

GLK12232-25-SM PCB 1.4 including all applicable extensions and combinations:

-WB (display colour)
-V, -E (power and temperature options)

### Reason for Change:

A firmware change has been implemented to compensate for some timing differences with the new black bezel displays (please see PCN 2007-05-22-01). The startup was delayed to allow the display to initialize properly.

### Product Change:

The GLK12232-25-SM PCB 1.4 firmware v2.2 is now superseded by firmware v2.3.

### New Firmware Version:

GLK12232-25-SM PCB 1.4	v2.3
------------------------	------

### Schedule of Change:

August 1, 2007

## Documentation Revision

Revision	Changes	Date	Author
1.0	Initial Release	Aug 1/07	R Malinis

## Contact Information:

Adam Lintott (Sales Manager): [alintott@matrixorbital.ca](mailto:alintott@matrixorbital.ca)

## Reference Documents/Attachments:

Location: <http://www.matrixorbital.ca/manuals/>

## Approvals:

<i>Documentation / Tech Support</i>	<i>Engineer</i>	<i>Production</i>	<i>Sales</i>
Larry Grieve	Larry Grieve	Mike McTavish	Adam Lintott